



## DOW CORNING CORPORATION Material Safety Data Sheet

Page: 1 of 8

### DOW CORNING(R) 92-023 PRIMER

#### 1. IDENTIFICATION OF THE SUBSTANCE AND OF THE COMPANY

Dow Corning Corporation South Saginaw Road Midland, Michigan 48686 24 Hour Emergency Telephone: (989) 496-5900

Customer Service: (989) 496-6000 Product Disposal Information: (989) 496-6315

CHEMTREC: (800) 424-9300

MSDS No.: 01170988 Revision Date: 2004/08/23

Generic Description: Silicone in solvent

Physical Form: Liquid

Color: See product name Odor: Some odor

NFPA Profile: Health 2 Flammability 3 Instability/Reactivity 0

Note: NFPA = National Fire Protection Association

#### 2. OSHA HAZARDOUS COMPONENTS

CAS Number	Wt %	Component Name
142-82-5	> 60.0	Heptane
2551-83-9	7.0 - 13.0	Allyltrimethoxysilane
5593-70-4	5.0 - 10.0	Tetrabutyl titanate

The above components are hazardous as defined in 29 CFR 1910.1200.

#### 3. EFFECTS OF OVEREXPOSURE

#### Acute Effects

Eye:

Direct contact may cause moderate irritation.

Skin:

May cause moderate irritation.

Inhalation:

Vapor may irritate nose and throat. Vapor overexposure may cause drowsiness.

Oral:

May cause vomiting. Aspiration of liquid while vomiting may injure lungs seriously.

#### Prolonged/Repeated Exposure Effects

Skin:

Repeated or prolonged exposure may irritate seriously. Repeated or prolonged contact may cause defatting and drying of skin which may result in skin irritation and dermatitis.

Inhalation:

Product generates methyl alcohol which may cause blindness and damage to nervous system. Overexposure by inhalation may injure the following organ(s): Heart. Liver.

Kidneys. Nervous system. Bone marrow.

## DOW CORNING CORPORATION Material Safety Data Sheet

Page: 2 of 8

### DOW CORNING(R) 92-023 PRIMER

Oral:

Product generates methyl alcohol which may cause blindness and possibly death if

swallowed.

Signs and Symptoms of Overexposure

No known applicable information.

Medical Conditions Aggravated by Exposure

No known applicable information.

The above listed potential effects of overexposure are based on actual data, results of studies performed upon similar compositions, component data and/or expert review of the product. Please refer to Section 11 for the detailed toxicology information.

#### 4. FIRST AID MEASURES

Eye:

Immediately flush with water for 15 minutes. Get medical attention.

Skin:

Remove from skin and wash thoroughly with soap and water or waterless cleanser. Get

medical attention if irritation or other ill effects develop or persist.

Inhalation:

Remove to fresh air. Get medical attention if ill effects persist.

Oral:

Get immediate medical attention. Only induce vomiting at the instructions of a physician.

Never give anything by mouth to an unconscious person.

Comments:

Treat same as methyl alcohol poisoning.

#### 5. FIRE FIGHTING MEASURES

Flash Point:

9 °F / -12.8 °C (Pensky-Martens Closed Cup)

Autoignition

Not determined.

Temperature:

Flammability Limits in Air: Not determined.

Extinguishing Media:

On large fires use dry chemical, foam or water spray. On small fires use carbon dioxide (CO2), dry chemical or water spray. Water can be used to cool fire exposed containers.

Fire Fighting Measures:

Self-contained breathing apparatus and protective clothing should be worn in fighting large fires involving chemicals. Determine the need to evacuate or isolate the area according to your local emergency plan. Use water spray to keep fire exposed containers

cool.

Unusual Fire Hazards:

Vapors are heavier than air and may travel to a source of ignition and flash back. Static electricity will accumulate and may ignite vapors. Prevent a possible fire hazard by bonding and grounding or inert gas purge.

#### Hazardous Decomposition Products

Thermal breakdown of this product during fire or very high heat conditions may evolve the following hazardous

## DOW CORNING CORPORATION Material Safety Data Sheet

Page: 3 of 8

### DOW CORNING(R) 92-023 PRIMER

decomposition products: Carbon oxides and traces of incompletely burned carbon compounds. Silicon dioxide. Metal oxides. Formaldehyde.

#### 6. ACCIDENTAL RELEASE MEASURES

Containment/Clean up:

Remove possible ignition sources. Determine whether to evacuate or isolate the area according to your local emergency plan. Observe all personal protection equipment recommendations described in Sections 5 and 8. For large spills, provide diking or other appropriate containment to keep material from spreading. If diked material can be pumped, store recovered material in appropriate container. Clean up remaining materials from spill with suitable absorbant. Clean area as appropriate since spilled materials, even in small quantities, may present a slip hazard. Final cleaning may require use of steam, solvents or detergents. Dispose of saturated absorbant or cleaning materials appropriately, since spontaneous heating may occur. Local, state and federal laws and regulations may apply to releases and disposal of this material, as well as those materials and items employed in the cleanup of releases. You will need to determine which federal, state and local laws and regulations are applicable. Sections 13 and 15 of this MSDS provide information regarding certain federal and state requirements.

Note: See section 8 for Personal Protective Equipment for Spills. Call Dow Corning Corporation, (989) 496-5900, if additional information is required.

#### 7. HANDLING AND STORAGE

Use with adequate ventilation. Product evolves flammable methyl alcohol when exposed to water or humid air. Provide ventilation during use to control exposure within Section 8 guidelines or use air-supplied or self-contained breathing apparatus. Product evolves n-butyl alcohol when exposed to water or humid air. Provide ventilation during use to control n-butyl alcohol within exposure guidelines or use respiratory protection. Avoid eye contact. Avoid skin contact. Avoid breathing vapor, mist, dust, or fumes. Keep container closed. Do not take internally.

Static electricity will accumulate and may ignite vapors. Prevent a possible fire hazard by bonding and grounding or inert gas purge. Keep container closed and away from heat, sparks, and flame. Keep container closed and store away from water or moisture.

#### 8. EXPOSURE CONTROLS / PERSONAL PROTECTION

#### Component Exposure Limits

CAS Number	Component Name	Exposure Limits
142-82-5	Heptane	OSHA PEL (final rule): TWA 500 ppm, 2000 mg/m3. ACGIH TLV: TWA 400 ppm, STEL 500 ppm.
2551-83-9	Allyltrimethoxysilane	See methyl alcohol comments.
5593-70-4	Tetrabutyl titanate	See n-butyl alcohol comments.

Methyl alcohol forms on contact with water or humid air. Provide adequate ventilation to control exposures within guidelines of OSHA PEL: TWA 200 ppm and ACGIH TLV-skin: TWA 200 ppm, STEL 250 ppm. n-Butyl alcohol is formed on contact with water or humid air. Provide adequate ventilation to control exposures within guidelines of OSHA PEL (final rule): TWA 100 ppm and ACGIH TLV: 20 ppm.

#### **Engineering Controls**

## DOW CORNING CORPORATION Material Safety Data Sheet

Page: 4 of 8

### DOW CORNING(R) 92-023 PRIMER

Local Ventilation: General Ventilation: Recommended. Recommended.

Personal Protective Equipment for Routine Handling

Eyes:

Use proper protection - safety glasses as a minimum.

Skin:

Wash at mealtime and end of shift. If skin contact occurs, change contaminated clothing as soon as possible and thoroughly flush affected areas with cool water. Chemical

protective gloves are recommended.

Suitable Gloves:

Silver Shield(R). 4H(R). Teflon(R). Viton(R).

Inhalation:

Use respiratory protection unless adequate local exhaust ventilation is provided or air sampling data show exposures are within recommended exposure guidelines. Industrial Hygiene Personnel can assist in judging the adequacy of existing engineering controls.

Suitable Respirator:

General and local exhaust ventilation is recommended to maintain vapor exposures below recommended limits. Where concentrations are above recommended limits as determined by air sampling or are unknown, appropriate respiratory protection should be worn. Follow OSHA Respirator Regulations (29 CFR 1910.134) and use NIOSH/MSHA approved respirators.

#### Personal Protective Equipment for Spills

Eyes:

Use full face respirator.

Skin:

Wash at mealtime and end of shift. If skin contact occurs, change contaminated clothing as soon as possible and thoroughly flush affected areas with cool water. Chemical protective gloves are recommended.

Inhalation/Suitable

Respirator:

Respiratory protection recommended. Follow OSHA Respirator Regulations (29 CFR 1910.134) and use NIOSH/MHSA approved respirators. Protection provided by air purifying respirators against exposure to any hazardous chemical is limited. Use a positive pressure air supplied respirator if there is any potential for uncontrolled release, exposure levels are unknown, or any other circumstance where air purifying respirators may not provide adequate protection.

Precautionary Measures:

Avoid eye contact. Avoid skin contact. Avoid breathing vapor, mist, dust, or fumes. Keep container closed. Do not take internally. Use reasonable care.

Comments:

Product evolves flammable methyl alcohol when exposed to water or humid air. Provide ventilation during use to control exposure within Section 8 guidelines or use air-supplied or self-contained breathing apparatus. Product evolves n-butyl alcohol when exposed to water or humid air. Provide ventilation during use to control n-butyl alcohol within exposure guidelines or use respiratory protection.

## DOW CORNING CORPORATION Material Safety Data Sheet

Page: 5 of 8

### DOW CORNING(R) 92-023 PRIMER

Note: These precautions are for room temperature handling. Use at elevated temperature or aerosol/spray applications may require added precautions. For further information regarding aerosol inhalation toxicity, please refer to the guidance document regarding the use of silicone-based materials in aerosol applications that has been developed by the silicone industry (www.SEHSC.com) or contact the Dow Corning customer service group.

#### 9. PHYSICAL AND CHEMICAL PROPERTIES

Physical Form: Liquid

Color: See product name

Odor: Some odor

Specific Gravity @ 25°C: 0.71

Viscosity: 0.63 cSt

Freezing/Melting Point: Not determined.

Boiling Point: > 90 °C

Vapor Pressure @ 25°C: Not determined.

Vapor Density: Not determined. Solubility in Water: Not determined.

pH: Not determined.

Volatile Content: Not determined.

Note: The above information is not intended for use in preparing product specifications. Contact Dow Corning before writing specifications.

#### 10. STABILITY AND REACTIVITY

Chemical Stability:

Stable.

Hazardous

Hazardous polymerization will not occur.

Polymerization:

Conditions to Avoid:

None.

Materials to Avoid:

Oxidizing material can cause a reaction. Water, moisture, or humid air can cause

hazardous vapors to form as described in Section 8.

#### 11. TOXICOLOGICAL INFORMATION

#### Special Hazard Information on Components

#### Mutagens

CAS Number

Wt %

Component Name

2551-83-9

7.0 - 13.0

Allyltrimethoxysilane

Genetically active in IN VITRO assay(s).

#### 12. ECOLOGICAL INFORMATION

#### **Environmental Fate and Distribution**

Complete information is not yet available.



## DOW CORNING CORPORATION **Material Safety Data Sheet**

Page: 6 of 8

### DOW CORNING(R) 92-023 PRIMER

#### **Environmental Effects**

Complete information is not yet available.

#### Fate and Effects in Waste Water Treatment Plants

Complete information is not yet available.

**Ecotoxicity Classification Criteria** 

Hazard Parameters (LC50 or EC50)	High	Medium	Low	
Acute Aquatic Toxicity (mg/L)	<=1	>1 and <=100	>100	
Acute Terrestrial Toxicity	<=100	>100 and <= 2000	>2000	

This table is adapted from "Environmental Toxicology and Risk Assessment", ASTM STP 1179, p.34, 1993.

This table can be used to classify the ecotoxicity of this product when ecotoxicity data is listed above. Please read the other information presented in the section concerning the overall ecological safety of this material.

#### 13. DISPOSAL CONSIDERATIONS

#### RCRA Hazard Class (40 CFR 261)

When a decision is made to discard this material, as received, is it classified as a hazardous waste? Yes

Characteristic Waste:

Ignitable:

D001

D018

TCLP:

State or local laws may impose additional regulatory requirements regarding disposal.

Call Dow Coming Corporate Environmental Management, (989) 496-6315, if additional information is required.

#### 14. TRANSPORT INFORMATION

#### DOT Road Shipment Information (49 CFR 172.101)

Proper Shipping Name: HEPTANE SOLUTION

Hazard Class:

UN/NA Number:

UN1206

Packing Group:

Hazard Label(s):

FLAMMABLE LIQUID LABEL

#### Ocean Shipment (IMDG)

Proper Shipping Name:

HEPTANE SOLUTION

Hazard Class:

3

UN Number:

1206

## DOW CORNING CORPORATION **Material Safety Data Sheet**

Page: 7 of 8

### **DOW CORNING(R) 92-023 PRIMER**

Packing Group:

Hazard Label(s):

FLAMMABLE LIQUID

Marine Pollutant:

Not Applicable

Air Shipment (IATA)

Proper Shipping Name: HEPTANE SOLUTION

Hazard Class:

UN Number:

1206

Packing Group:

Hazard Label(s):

FLAMMABLE LIQUID

Call Dow Coming Transportation, (989) 496-8577, if additional information is required.

#### 15. REGULATORY INFORMATION

Contents of this MSDS comply with the OSHA Hazard Communication Standard 29 CFR 1910.1200.

TSCA Status:

All chemical substances in this material are included on or exempted from listing on the TSCA

Inventory of Chemical Substances.

#### EPA SARA Title III Chemical Listings

Section 302 Extremely Hazardous Substances:

None.

Section 304 CERCLA Hazardous Substances:

None.

#### Section 312 Hazard Class:

Acute: Yes Chronic: Yes Fire: Yes Pressure: No Reactive: No

#### Section 313 Toxic Chemicals:

None present or none present in regulated quantities.

#### Supplemental State Compliance Information

#### California

Warning: This product contains the following chemical(s) listed by the State of California under the Safe Drinking



## DOW CORNING CORPORATION Material Safety Data Sheet

Page: 8 of 8

### DOW CORNING(R) 92-023 PRIMER

Water and Toxic Enforcement Act of 1986 (Proposition 65) as being known to cause cancer, birth defects or other reproductive harm.

None known.

#### Massachusetts

wassachusetts		
CAS Number	Wt %	Component Name
142-82-5	> 60.0	Heptane
New Jersey		
CAS Number	Wt %	Component Name
142-82-5	> 60.0	Heptane
2551-83-9	7.0 - 13.0	Allyltrimethoxysilane
5593-70-4	5.0 - 10.0	Tetrabutyl titanate
Pennsylvania		
CAS Number	Wt %	Component Name
142-82-5	> 60.0	Heptane

#### 16. OTHER INFORMATION

2551-83-9

5593-70-4

Prepared by: Dow Corning Corporation

7.0 - 13.0

5.0 - 10.0

Allyltrimethoxysilane

Tetrabutyl titanate

These data are offered in good faith as typical values and not as product specifications. No warranty, either expressed or implied, is hereby made. The recommended industrial hygiene and safe handling procedures are believed to be generally applicable. However, each user should review these recommendations in the specific context of the intended use and determine whether they are appropriate.

(R) indicates Registered Trademark