

HD MicroSystems Material Safety Data Sheet

PT2574

Revised 4-SEP-2003 Printed 4-SEP-2003

CHEMICAL PRODUCT/COMPANY IDENTIFICATION

Tradenames and Synonyms

Pyralin(R) Polyimide Coating

Company Identification

MANUFACTURER/DISTRIBUTOR

HD MicroSystems Cheesequake Road Parlin New Jersey

08859

PHONE NUMBERS

Product Information : (800) 346-5656

Transport Emergency : (800) 424-9300 (Outside the US (703)

527-3887)

: (800) 441-7515 (Outside the US (302) Medical Emergency

774-1000)

COMPOSITION/INFORMATION ON INGREDIENTS

CAS Number Material Polyamic acid of Benzophenone 31942-21-9 10-30
Tetracarboxylic Dianhydride/4,4Oxydianiline/m-Phoryl 2-21-9 *n-Methylpyrrolidone Oxydianiline/m-Phenylenediamine Polymer

67-56-1 0.1-1 *Methanol Proprietary Ingredients

* Disclosure as a toxic chemical is required under Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR part 372.

HAZARDS IDENTIFICATION

Potential Health Effects

This product is a physical mixture. The health effects information about this product is based on the individual ingredients:

OVERVIEW

The most likely routes overexposure to this product are skin contact and inhalation. Skin irritation and/or other effects of skin contact are easily avoided by using proper gloves (see section titled GLOVES) and washing affected areas immediately if contact occurs. Volatile solvents will start evaporating during room temperature use of the product, such as thinning, pouring from jar to dispensing machine, and spin coating. Mist and solvent vapors will evolve if spray application is used.

During wafer drying, 125 - 150 C, and final curing, 350 - 450 C, the remaining solvent(s) will evaporate. Potential overexposure to other chemicals used in the operation such as wafer etchants and cleaners should also be considered. Well designed area and personal air sampling and analysis can show if exposures are within established limits. Properly designed local ventilation and process enclosure are effective ways to limit employee exposure where needed. In addition to meeting exposure limits, it is always prudent to use all practical means to minimize employee exposure to chemicals. A significant difference in overall exposure can be made with practical measures such as:

- Inhalation- minimizing by keeping jars of product covered
- Eye avoiding contact by wearing chemical splash goggles where there is splash potential
- Ingestion avoiding by washing hands before eating, drinking or smoking, and restricting these activities to outside the work area.

>>>Polyamic acid of Benzophenone Tetracarboxylic Dianhydride/4,4-Oxydianiline/m-Phenylenediamine (Polymer) ****Toxic effects described in animals include: BY SKIN OR EYE CONTACT: Skin irritation; Skin sensitization; Eye irritation.

>>>Methanol

Toxic effects described in animals include: By skin or eye contact: Skin irritation; Eye effects; Eye irritation; Nasal effects; By ingestion: Eye effects; Anaesthetic effects; Acidosis. Toxic effects of repeated or prolonged animal exposures include: By skin or eye contct: Death; Additional animal tests have shown: Developmental toxicity; No mutagenic toxicity. Human health effects of overexposure may include: By skin or eye contact: Skin irritation with discomfort or rash; Eye irritation with discomfort, tearing, or blurring of vision; By ingestion: Metabolic acidosis; By contact, inhalation or ingestion : Visual impairment; Temporary nervous system depression with anaesthetic effects, e.g., dizziness, headache, confusion, incoordination, and loss of consciousness; Nonspecific discomfort; e.g., nausea. headache or weakness; Irritation of the upper respiratory passages. Human effects of higher level acute, repeated, or chronic overexposure may include: By contact, inhalation or ingestion: Temporary nervous system effects, e.g.; muscular weakness and incoordination; Cardiovascular effects; Abnomial kidney function as detected by laboratory tests; Abnormal liver function as detected by laboratory tests; Fatality from gross overexposure. In addition: Skin permeation can occur in amounts capable of producing effects of systemic toxicity; Epidemiologic studies show no significant risk of human cancer from exposure to this component; Excessive human exposure to methanol may lead to fatigue, headache, naesthetic neurologic effects, and visual difficulties, ultimately including blindness.

>>>Proprietary Ingredient(s)
Toxic effects described in animals include: Skin irritation; Eye irritation.

Individuals may have increased susceptibility to the hazards of overexposure to ingredient(s) of this product if they have pre-existing diseases of the: Eyes; Cardiovascular system; Liver; Kidneys.

Inhalation of NMP may cause irritation of the nose and throat with sneezing, sore throat or runny nose; or non-specific effects such as headache, nausea and weakness.

Skin contact with NMP may cause skin irritation with itching, burning, redness, swelling or rash. Human experience or case reports have identified the following potential effects from overexposure: Prolonged contact may cause severe skin irritation with burning, redness, swelling, pain, blisters, cracking, or rash. There are inconclusive or unverified reports of human sensitization. Skin permeation may occur in amounts capable of producing the effects of systemic toxicity.

Eye contact with NMP may cause eye irritation with tearing, pain or blurred vision. Low vapor concentrations did cause eye irritation in some individuals.

Carcinogenicity Information - None of the components present in this material at concentrations equal to or greater than 0.1% are listed by IARC, NTP, OSHA or ACGIH as a carcinogen.

FIRST AID MEASURES

First Aid

INHALATION

If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Call a physician.

SKIN CONTACT

In case of contact, immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Call a physician. Wash contaminated clothing before reuse.

EYE CONTACT

In case of contact, immediately flush eyes with plenty of water for at least 15 minutes. Call a physician.

INGESTION

If swallowed, do not induce vomiting. Immediately give 2 glasses of water. Never give anything by mouth to an unconscious person. Call a physician.

Notes to Physicians

Activated charcoal mixture may be beneficial. Suspend 50 g activated charcoal in 400 mL water and mix well. Administer 5 mL/kg, or 350 mL for an average adult.

FIRE FIGHTING MEASURES

Flammable Properties

Flash Point Method : 155 F (68 C)

: Setaf

: Setaflash Closed Cup - SCC.

FIRE & EXPLOSION HAZARDS:

KEEP AWAY FROM SPARKS AND OPEN FLAMES. Do not smoke in area with open product; If the product may be heated above its flashpoint during processing, remove sources of ignition such as open sparks, flames or static discharge to prevent vapor ignition.

Extinguishing Media - Water Spray, Dry Chemical, Carbon Dioxide.

Fire Fighting Instructions

Wear full protective equipment. Thoroughly decontaminate all equipment used in firefighting efforts before returning to service.

Toxic decomposition products may form under fire conditions. (See Decomposition Section.); Wear a full facepiece, positive pressure, self-contained breathing apparatus (SCBA); Dispose of residues per federal, state, and local regulation. (See Waste Disposal Section.).

ACCIDENTAL RELEASE MEASURES

Safeguards (Personnel)

NOTE: Review FIRE FIGHTING MEASURES and HANDLING (PERSONNEL) sections before proceeding with clean-up. Use appropriate PERSONAL PROTECTIVE EQUIPMENT during clean-up.

Evacuate personnel, thoroughly ventilate area, use self-contained breathing apparatus.

Spill Clean Up

Spill, Leak or Release: FOR SMALL SPILLS, absorb on rags, sand or other absorbent material;

FOR LARGE SPILLS, get workers out of affected area. If flammable liquids or vapors may be present, turn off electrical devices or other sources of sparks or flames.

WEAR PROTECTIVE EQUIPMENT. Use supplied-air respiratory protection if vapor concentrations are not known; Contain spill at source by diking or absorbing with sand. Do not allow spill to spread to or intentionally flush to sewer or ground. Wash area thoroughly. Adequately ventilate area; Spill residue, cleaning rags and absorbent may be considered hazardous. (See Waste Disposal Section.).

HANDLING AND STORAGE

Handling (Personnel)

Contaminated clothing and cleaning materials, etc. should be considered hazardous until decontaminated or properly disposed of. (See Waste Disposal Section.).

Storage

Store product in a refrigerated location (0-4F), away from sunlight or ultraviolet light to ensure product viscosity stability.

EXPOSURE CONTROLS/PERSONAL PROTECTION

Engineering Controls

Use only with adequate ventilation.

Adequate local ventilation should be used to keep exposures below applicable limits; Other engineering controls such as totally enclosed handling systems are also preferred; Respiratory protection will be needed if exposures can not be kept below applicable limits by other means.

Personal Protective Equipment

Respiratory Protection:

Selection of a suitable respirator will depend on the properties of the contaminant(s) and their actual or expecte air concentration(s) versus applicable limits. Consult ANSI Standard Z88.2 for decision logic to select appropriate NIOSH/MESA approved respirators; If respirators are needed to meet applicable limits, a respiratory protection group up to the level of OSHA Standard 29 CFR 1910.134 is mandatory. This includes air monitoring selection, medical approval training, fit testing, inspection, maintenance, cleaning, storage, etc.

Gloves should be used when the possibility of skin contact exists; The suitability of a particular glove and glove material should be determined as part of an overall glove program. Considerations may include chemical breakthrough time; permeation rate; abrasion, cut and puncture resistance; flexibility; duration of contact; etc.

Other Protection Practices:

Appropriate eye protection such as chemical splash goggles should be used if the possibility of eye contact exists; Protective outer clothing should beused where the possibility of body contact exists. Contaminated work clothing should not be allowed out of the workplace; Do not smoke, consume or store food or drinks in areas where the product is handled or stored. After handling the product, wash hands thoroughly before leaving the work area; Additional engineering controls, work practices and training may be required depending on exposure levels. These are discussed in the OSHA Respiratory Protection Standard (29 CFR 1910.134) and OSHA Hazard Communication Standard (29 CFR 1910.1200); Do not breath dust. Avoid contact with eyes, skin, or clothing. Wash thoroughly after handling.

Exposure Guidelines

Applicable Exposure Limits

n-Methylpyrrolidone
ppr. (OSHA) : None Established TLV (ACGIH) : None Established

AEL * (DuPont) WEEL (AIHA)

: 5 ppm, 8 & 12 Hr. TWA, Skin

: 10 ppm, 8 Hr. TWA, Skin

Methanol

PEL (OSHA) TLV (ACGIH)

: 200 ppm, 260 mg/m3, 8 Hr. TWA : 200 ppm, 8 Hr. TWA, Skin

STEL 250 ppm

: 200 ppm, 8 & 12 Hr. TWA, Skin

* AEL is DuPont's Acceptable Exposure Limit. Where governmentally imposed occupational exposure limits which are lower than the AEL are in effect, such limits shall take precedence.

PHYSICAL AND CHEMICAL PROPERTIES

Physical Data

: Viscous Liquid.

Form Color

Solubility in Water

: Brown.

: Slight : Aromatic.

STABILITY AND REACTIVITY

Chemical Stability - Stable at normal conditions.

Incompatibility with Other Materials - Avoid contact with: Reducing agents; Oxidizing agents; Bases; Acids; Chloroform in the presence of a strong base; Magnesium; Bromine; Nitric acid.

Decomposition - Decomposition products at high temperature may include: Carbon monoxide (CO); Nitrogen oxides; Carbon monoxide, carbon dioxide, water, silicon oxides.

Polymerization - The product may polymerize endothermically if exposed to temperatures over 90 F, ultraviolet light or free radical initiators. This may increase viscosity.

TOXICOLOGICAL INFORMATION

Animal Data

>>>Methanol

Inhalation 1 hour LC50: > 145,000 ppm in rats Oral LD50: 9,100 mg/kg in rats. Skin absorption LD50: > 15,840 mg/kg in rabbits

>>>N-Methyl-2-Pyrollidone

Inhalation 4 hour ALC: 1.7 mg/L in rats. Skin absorption LD50: > 8,000 mg/kg in rabbits Oral LD50: 4,320 mg/kg

DISPOSAL CONSIDERATIONS

Waste Disposal

Components of this product may be considered hazardous; Consult applicable Federal, State, and local regulations for allowable disposal methods.

Container Disposal

Empty product containers should be considered hazardous until decontaminated or properly disposed of. (See Waste Disposal Section.).

REGULATORY INFORMATION

U.S. Federal Regulations - This product complies with TSCA inventory reporting requirements.

State Regulations (U.S.) - WARNING - SUBSTANCES KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER, BIRTH DEFECTS OR OTHER REPRODUCTIVE HARM - n-Methylpyrrolidone

OTHER INFORMATION

Additional Information

The data in this Material Safety Data Sheet relates only to the specific material designated herein and does not relate to use in combination with any other material or in any process.

Responsibility for MSDS : HD MicroSystems (TM)
Address : Cheesequake Road
Parlin, NJ 08859
Telephone : 1-800-346-5656

End of MSDS